

DEMPSTER NO. 10 STEEL WINDMILL PARTS




Fig. 1148

See Numerical List for Prices

DEMPSTER NO. 8 STEEL MILL PARTS




Fig. 1167

See Numerical List for Prices .

DEMPSTER IMPROVED STEEL WINDMILL

PARTS

• No. 7




Fig. 1124

See Numerical List for Prices

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
2Q	\$2.87	Vane casting	8' No. 8
2QQ	3.99	Vane casting	10' No. 8
2Z	5.81	Vane casting	12' No. 8
5Q	1.82	Rocker arm	8' No. 8
5QQ	2.73	Rocker arm	10' No. 8
5Z	4.20	Rocker arm	12' No. 8
6Q	.42	Flat bar connection	8' No. 8
6QQ	.67	Flat bar connection	10' No. 8
6Z	1.01	Flat bar connection	12' No. 8
7	.42	Swivel casting	All 6'-8'-10' mills
7C	.67	Swivel casting	All 12' mills
8	.42	Swivel casting	All 6'-8'-10' mills
8C	.67	Swivel casting	All 12' mills
9	.25	Sheave	8'-10' Nos. 7-8
9C	.25	Sheave	12' Nos. 7-8
9N	.17	Sheave	6' No. 7
9½	.17	Sheave	8' No. 8
10Q	.84	Pitman	8' No. 8
10QQ	1.54	Pitman	10' No. 8
10Z	2.24	Pitman	12' No. 8
10½Q	.25	Pitman box	8' No. 8
10½QQ	.25	Pitman box	10' No. 8
10½Z	.50	Pitman box	12' No. 8
11	.17	Eye pump pin	All mills
11Q	.67	Swivel casting	8' No. 8
11QQ	.67	Swivel casting	8'-10' Nos. 8-10
11Z	.92	Swivel casting	12' Nos. 8-10
12Q	.42	Pin for No. 2Q	8' No. 8
12QQ	.67	Pin for No. 2QQ	10' No. 8
12Z	.92	Pin for No. 2Z	12' No. 8
14Q	.25	Pin for No. 5Q	8' No. 8
14QQ	.67	Pin for No. 5QQ	10' No. 8
14Z	.76	Pin for No. 5Z	12' No. 8
15Q	.25	Pin for Nos. 5Q and 6Q	8' No. 8
15QQ	.34	Pin for Nos. 5QQ and 6QQ	10' No. 8
15Z	.42	Pin for Nos. 5Z and 6Z	12' No. 8
16	2.31	Storm stay for W. T.	8' Nos. 7-10; 10' Nos. 7-8-10
16N	1.54	Storm stay for W. T.	6' No. 7; 8' No. 8
16U	2.94	Storm stay for W. T.	12' Nos. 7-8-10
17Q	.25	Pin for Nos. 5Q and 10Q	8' No. 8
17QQ	.34	Pin for Nos. 5QQ and 10QQ	10' No. 8
17Z	.42	Pin for Nos. 5Z and 10Z	12' No. 8
18Q	3.78	Crank shaft	8' No. 8
18QQ	5.32	Crank shaft	10' No. 8
18Z	12.95	Crank shaft	12' No. 8
20	1.34	Flat bar connection, O. S.	6'-8'-10' mills
A20	.50	Flat bar connection	All 6'-8'-10' mills
020	1.68	Flat bar connection	All 12' mills
21	.50	Splice irons, "pair"	All 6'-8'-10' mills
21½	.92	Splice irons, "pair"	All 12' mills
25QQ	1.18	Main box, O. S.	8' No. 8
025QQ	1.34	Main box, O. S.	10' No. 8
25S	1.34	Long shaft box	8' No. 7
25U	2.03	Long shaft box	12' No. 7
25V	1.54	Long shaft box	10' No. 7
25Z	1.68	Main box, O. S.	12' No. 8
25½N	1.01	Long shaft box	6' No. 7
25½Q	.76	Main shaft box	8' No. 8
25½QQ	1.26	Main shaft box	10' No. 8
25½Z	1.89	Main shaft box	12' No. 8
26S	1.18	Short shaft box	8' No. 7
26U	1.89	Short shaft box	12' No. 7
26V	1.34	Short shaft box	10' No. 7
26½N	1.01	Short shaft box	6' No. 7

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
27Q	.17	½" plug for grease cup	8'-10'-12' No. 8; 8'-10'-12' No. 10; 6' No. 7.
27L	2.24	Guide casting for sq. bar	10' No. 7
27M	1.89	Guide casting for sq. bar	8' No. 7
27N	1.54	Guide casting for sq. bar	6' No. 7
27U	2.52	Guide casting for sq. bar	12' No. 7
28Q	.34	1" plug for grease cup	8'-10'-12' No. 8; 8'-10'-12' No. 10
49½	1.68	Vane casting with truss lug	8' No. 7
49½B	2.03	Vane casting with truss lug	10' No. 7
49½N	1.34	Vane casting with truss lug	6' No. 7
49½U	2.73	Vane casting with truss lug	12' No. 7
50A	.67	Brake bumper	8' No. 7
50B	.84	Brake bumper	10' No. 7
50C	1.18	Brake bumper	12' No. 7
50N	.50	Brake bumper	6' No. 7
57C	2.80	Bed plate, 3" steel tower, 2½" pipe	All 12' mills
O57C	2.80	Bed plate, 3" steel tower	6' No. 7; 8' No. 8
57CC	2.80	Bed plate, 3" tower, 2" pipe	10' No. 8; 8'-10' No. 10
57NN	2.38	Bed plate, wood or steel tower	6' No. 7; 8' No. 8
57S	1.89	Bed plate, 3-post steel tower	10' No. 8; 8'-10' No. 10
57SS	1.89	Bed plate, 3-post steel tower	8' No. 8; 6' No. 7
58BB	1.82	Storm stay, wood or steel tower	10' Nos. 8-10; 8' Nos. 7-10
O58C	2.80	Storm stay, 3" steel tower	6' No. 7; 8' No. 8
58CC	2.80	Storm stay, 3" tower, 2" pipe	8'-10' No. 10; 10' No. 8
58Q	1.68	Storm stay, wood or steel tower	8' No. 8; 6' No. 7
58S	.98	Storm stay, 3-post steel tower	10' No. 8; 8'-10' No. 10
58SS	.98	Storm stay, 3-post steel tower	8' No. 8; 6' No. 7
58½	2.10	Storm stay, steel tower	10' No. 7, O. S.
58½	2.80	Storm stay, steel tower	All 12' mills
59N	.67	Collar for vane pipe	6' No. 7
59S	.34	Collar for vane pipe	All 8' mills
59U	.92	Collar for vane pipe	All 12' mills
59V	.42	Collar for vane pipe	All 10' mills
66	.84	Swivel casting	8'-10' No. 7
66C	1.09	Swivel casting	12' No. 7
66N	.67	Swivel casting	6' No. 7
073M	1.18	Brake casting	8' No. 7
073N	1.01	Brake casting	6' No. 7
073Q	.92	Brake casting	8' No. 8
073QQ	1.01	Brake casting	10' No. 8
073U	2.03	Brake casting	12' No. 7
073V	1.54	Brake casting	10' No. 7
73Z	2.10	Brake casting	12' No. 8
74Q	.08	Key for No. 75Q	8' No. 8
74QQ	.08	Key for No. 75QQ	10' No. 8
74Z	.42	Key for No. 75Z	12' No. 8
75N	3.08	Large rim gear	6' No. 7
75Q	3.57	Large rim gear	8' No. 8
75QQ	6.30	Large rim gear	10' No. 8
75S	3.78	Large rim gear	8' No. 7
75U	9.45	Large rim gear	12' No. 7
75V	6.58	Large rim gear	10' No. 7
75Z	9.10	Large rim gear	12' No. 8
76N	1.01	Small rim gear	6' No. 7
76QQ	2.31	Small rim gear	10' No. 8
76S	1.26	Small rim gear	8' Nos. 7-8
76U	3.36	Small rim gear	12' No. 7
76V	1.68	Small rim gear	10' No. 7
76Z	3.36	Small rim gear	12' No. 8
77A	.27	Set collar	8' No. 7
77B	.42	Set collar	10' No. 7
77C	1.26	Set collar	12' No. 7

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
77N	.25	Set collar	6' No. 7
79	1.01	Upper guide casting	8'-10' No. 7
79C	1.54	Upper guide casting	12' No. 7
79N	.84	Upper guide casting	6' No. 7
79½	1.01	Lower guide casting	8'-10' No. 7
79½N	.84	Lower guide casting	6' No. 7
79½Q	.42	Lower guide casting	8' No. 8
79½QQ	.42	Lower guide casting	10' No. 8; 8'-10' No. 10
79½U	1.01	Lower guide casting	12' No. 7
79½Z	.57	Lower guide casting	12' Nos. 8-10
85	.17	Eye bolt for No. 130	8'-10'-12' Nos. 8-10
90	2.03	Bed plate for wood tower	8'-10' No. 7
90C	3.08	Bed plate for wood tower	12' Nos. 7-8
90N	1.68	Bed plate for wood tower	6' No. 7; 8' No. 8
99	.84	Vane brace	8' Nos. 8-10
99A	.84	Vane brace	8' No. 7
99B	1.18	Vane brace	10' Nos. 7-8-10
99C	1.68	Vane brace	12' Nos. 7-8-10
99N	.67	Vane brace	6' No. 7
99½	.84	Vane truss rod	8' Nos. 8-10
99½N	.67	Vane truss rod	8' No. 7
99½B	1.18	Vane truss rod	10' Nos. 7-8-10
99½C	1.34	Vane truss rod	12' No. 7
99½N	.50	Vane truss rod	6' No. 7
99½Z	1.68	Vane truss rod	12' Nos. 8-10
102	.84	Pull out chain	8' Nos. 8-10
102A	1.01	Pull out chain	8' No. 7
102B	1.34	Pull out chain	10' Nos. 7-8-10
102C	1.89	Pull out chain	12' Nos. 7-8-10
102N	.84	Pull out chain	6' No. 7
104	.34	Swivel rod with swivel, ¼"x5'6"	6' No. 7; 8'-10' No. 10
104J	.50	Swivel rod with swivel, ¼"x6'8"	12' No. 10
108	1.28	Wrist pin	8'-10' No. 7
108C	2.38	Wrist pin	12' No. 7
108N	1.01	Wrist pin	8' No. 7
109	.17	Outside corner washer	All steel towers
109½	.17	Inside corner washer	All steel towers
111A	1.26	Short shaft	8' No. 7
111C	3.22	Short shaft	12' No. 7
111N	1.01	Short shaft	6' No. 7
111V	1.54	Short shaft	10' No. 7
112A	2.10	Long shaft	8' No. 7
112C	6.09	Long shaft	12' No. 7
112N	1.68	Long shaft	6' No. 7
112Q	2.24	Long shaft	8' No. 8
112QQ	2.94	Long shaft	10' No. 8
112V	3.64	Long shaft	10' No. 7
112Z	5.74	Long shaft	12' No. 8
114N	.50	Brake band	6' No. 7
114S	.50	Brake band	8' Nos. 7-8
114U	1.54	Brake band	12' Nos. 7-8
114V	1.01	Brake band	10' Nos. 7-8
116N	.84	Sheave arm	6' No. 7
116QQ	1.89	Sheave arm	10' No. 8
116S	1.18	Sheave arm	8' Nos. 7-8
116U	2.03	Sheave arm	12' No. 7
116V	1.68	Sheave arm	10' No. 7
116Z	5.60	Sheave arm	12' No. 8
117A	1.34	Pitman	8' No. 7
117L	1.68	Pitman	10' No. 7
117N	1.01	Pitman	6' No. 7
117U	2.52	Pitman	12' No. 7
118A	1.01	Brake lever	8' No. 7

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
118L	1.18	Brake lever	10' No. 7
118N	.50	Brake lever	6' No. 7
118QQ	.50	Brake lever	8' No. 8
0118QQ	1.01	Brake lever	10' No. 8
118U	1.34	Brake lever	12' No. 7
118Z	1.89	Brake lever	12' No. 8
119Q	.84	Crank shaft box, O. S.	8' No. 8
119QQ	1.01	Crank shaft box, O. S.	10' No. 8
119Z	1.18	Crank shaft box, O. S.	12' No. 8
119½Q	.42	Shaft box	8' Nos. 8-10
119½QQ	.50	Shaft box	10' Nos. 8-10
119½Z	.92	Shaft box	12' Nos. 8-10
120A	1.68	Guide casting	8' No. 7
120L	2.38	Guide casting	10' No. 7
120N	1.18	Guide casting	6' No. 7
120Q	.84	Rear main shaft box, O. S.	8' No. 8
120QQ	1.01	Rear main shaft box, O. S.	10' No. 8
120U	2.73	Guide casting	12' No. 7
120Z	1.18	Rear main shaft box, O. S.	12' No. 8
120½Q	.42	Rear main shaft box	8' No. 8
120½QQ	.50	Rear main shaft box	10' No. 8
120½Z	.76	Rear main shaft box	12' No. 8
121Q	.34	Gear cover	8' No. 8
121QQ	.76	Gear cover	10' No. 8
121Z	1.34	Gear cover	12' No. 8
122	.34	Hook eye for regulator	8'-10' Nos. 7-8
122C	.67	Hook eye for regulator	12' Nos. 7-8
122N	.20	Hook eye for regulator	6' No. 7
123	.34	Eye bolt for regulator, O. S.	8'-10' No. 8
123A	.34	Eye bolt for regulator	8' No. 7
123B	.34	Eye bolt for regulator	10' No. 7
123C	.50	Eye bolt for regulator, O. S.	12' Nos. 7-8
123N	.20	Eye bolt for regulator	6' No. 7
124	.34	Turn buckle for regulator, O. S.	8'-10' No. 8
124	.34	Turn buckle for regulator, N. S.	8'-10' No. 7
124C	.67	Turn buckle for regulator	12' No. 8
124U	.67	Turn buckle for regulator	12' No. 7
125	.34	Hook bolt for regulator	6' No. 7
125A	.34	Hook bolt for regulator, O. S.	8' No. 8
125B	.50	Hook bolt for regulator, O. S.	10' No. 8
125C	.59	Hook bolt for regulator, O. S.	12' Nos. 7-8
125L	.50	Hook bolt for regulator	10' No. 7
125M	.34	Hook bolt for regulator	8' No. 7
127Q	.92	Flat bar	8' No. 8
127QQ	1.34	Channel bar	10' No. 8; 8'-10' No. 10
127Z	2.03	Channel bar	12' Nos. 8-10
128A	1.89	Spring for regulator, O. S.	8' No. 7
128B	2.38	Spring for regulator	10' No. 7
128C	6.09	Spring for regulator	12' No. 7
128N	1.34	Spring for regulator	6' No. 7
130	.92	Pull out lever	All 6'-8'-10'-12' mills
132	.50	Wood box in pitman for wrist pin....	8'-10' No. 7
132N	.34	Wood box in pitman for wrist pin....	6' No. 7
132U	.67	Wood box in pitman for wrist pin....	12' No. 7
134	.17	Steel washer for bearing	8'-10' No. 7
134C	.17	Steel washer for bearing	12' Nos. 7-8-10
134N	.17	Steel washer for bearing	6' No. 7
134Q	.17	Steel washer for bearing	8' No. 8
134QQ	.17	Steel washer for bearing	10' No. 8; 8'-10' No. 10
135	.08	Steel washer for wrist pin	6'-8'-10' No. 7
135C	.17	Steel washer for wrist pin	12' No. 7
136A	.34	Short wheel circle	8' Nos. 7-8-10
136B	.34	Short wheel circle	10' Nos. 7-8-10

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
136C	.84	Short wheel circle	12' Nos. 7-8-10
136N	.34	Short wheel circle	6' No. 7
137A	.76	Long wheel circle	8' Nos. 7-8-10
137B	.76	Long wheel circle	10' Nos. 7-8-10
137C	1.61	Long wheel circle	12' Nos. 7-8-10
137N	.59	Long wheel circle	6' No. 7
138A	.84	Fan only	All 8'-10' mills
138C	1.82	Fan only	12' Nos. 7-8-10
138N	.59	Fan only	6' No. 7
140A	4.41	Vane pipe	All 8' mills
140B	7.28	Vane pipe	All 10' mills
140C	12.39	Vane pipe	All 12' mills
140N	2.52	Vane pipe	All 6' mills
141	.17	Swivel only for 104	All 6'-8'-10' mills
141C	.34	Swivel only for 104	All 12' mills
142A	1.05	Wheel arm	8' Nos. 7-8
142B	1.47	Wheel arm	10' Nos. 7-8
142C	2.45	Wheel arm	12' No. 8
142N	.84	Wheel arm	6' No. 7
142U	2.45	Wheel arm	12' No. 7
143A	2.03	Wheel spider	8' Nos. 7-8
143B	3.92	Wheel spider	10' Nos. 7-8
143C	6.58	Wheel spider	12' Nos. 7-8
143N	1.68	Wheel spider	6' No. 7
144A	.92	Brace spider	8' Nos. 7-8
144B	1.68	Brace spider	10' Nos. 7-8
144C	2.52	Brace spider	12' Nos. 7-8
144N	.84	Brace spider	6' No. 7
145L	5.04	Square bar	10' No. 7
145M	4.06	Square bar	8' No. 7
145N	2.52	Square bar	6' No. 7
145U	7.56	Square bar	12' No. 7
146L	1.18	Long rod for guide support	10' No. 7
146M	.84	Long rod for guide support	8' No. 7
146N	.67	Long rod for guide support	6' No. 7
146U	1.68	Long rod for guide support	12' No. 7
147L	.84	Short rod for guide support	10' No. 7
147M	.67	Short rod for guide support	8' No. 7
147N	.50	Short rod for guide support	6' No. 7
147U	.84	Short rod for guide support	12' No. 7
148L	.67	Flat side brace for guide	10' No. 7
148M	.50	Flat side brace for guide	8' No. 7
148N	.42	Flat side brace for guide	6' No. 7
148U	.67	Flat side brace for guide	12' No. 7
149N	.34	Staple for shaft box	6' No. 7
149QQ	.42	Staple for shaft box	10' Nos. 7-8
149S	.42	Staple for shaft box	8' Nos. 7-8
149Z	.67	Staple for shaft box	12' Nos. 7-8
150N	.34	Top babbitt shaft box	6' No. 7
150QQ	.42	Top babbitt shaft box	10' Nos. 8-10
150S	.34	Top babbitt shaft box	All 8' mills
150U	.92	Top babbitt shaft box	12' No. 7
150V	.50	Top babbitt shaft box	10' No. 7
150Z	.92	Top babbitt shaft box	12' Nos. 8-10
151N	.34	Bottom babbitt shaft box	6' No. 7
151QQ	.42	Bottom babbitt shaft box	10' Nos. 8-10
151S	.34	Bottom babbitt shaft box	All 8' mills
151U	.92	Bottom babbitt shaft box	12' No. 7
151V	.50	Bottom babbitt shaft box	10' No. 7
151Z	.92	Bottom babbitt shaft box	12' Nos. 8-10
152L	1.01	Upper pitman pin for sq. bar	10' No. 7
152M	.67	Upper pitman pin for sq. bar	8' No. 7
152N	.59	Upper pitman pin for sq. bar	6' No. 7

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
152U	2.03	Upper pitman pin for sq. bar	12' No. 7
153L	.50	Cap for No. 27 guide casting	10' No. 7
153M	.42	Cap for No. 27 guide casting	8' No. 7
153N	.34	Cap for No. 27 guide casting	6' No. 7
153U	.50	Cap for No. 27 guide casting	12' No. 7
154	.17	Fan plate	All 8'-10' mills
154C	.25	Fan plate	All 12' mills
154N	.17	Fan plate	6' No. 7
155	.17	Fan ear	All 8'-10' mills
155C	.17	Fan ear	12' Nos. 8-10
155N	.17	Fan ear	8' No. 7
155U	.25	Fan ear	12' No. 7
156	.25	Nut for upper pitman pin	8'-10'-12' No. 7
156N	.20	Nut for upper pitman pin	6' No. 7
157A	.17	Key for 143A	8' Nos. 7-8
157B	.17	Key for 143B	10' Nos. 7-8
157C	.42	Key for 143C	12' Nos. 7-8
157N	.17	Key for 143N	6' No. 7
158	.25	Brace for sheave arm	8' Nos. 8-10
158L	.34	Brace for sheave arm	10' No. 7
158M	.25	Brace for sheave arm	8' No. 7
158N	.25	Brace for sheave arm	6' No. 7
158QQ	.34	Brace for sheave arm	10' Nos. 8-10
158U	.84	Brace for sheave arm	12' No. 7
158Z	.84	Brace for sheave arm	12' No. 8
159	.42	Arm for vane spring	6'-8'-10' No. 7
159U	.84	Arm for vane spring	12' No. 7
161	.25	Storm stay block	All mills
162	.25	Wood block for No. 120	6'-8' No. 7
162L	.25	Wood block for No. 120	10' No. 7
162U	.42	Wood block for No. 120	12' No. 7
163	.17	Vane bumper spring	All mills
164	.25	Vane bumper bolt	All mills
165A	.25	Clip for vane	8' No. 7
165B	.25	Clip for vane	10' No. 7
165C	.50	Clip for vane	12' No. 7
165N	.20	Clip for vane	6' No. 7
166	.25	Large cover for oil box	All 8'-10'-12' mills
166N	.25	Large cover for oil box	6' No. 7
167	2.24	Vane sheet	8' No. 8
167B	2.38	Vane sheet	10' No. 8
167L	.25	Upper wood block in pitman	10' No. 7
167U	.34	Upper wood block in pitman	12' No. 7
167Z	4.20	Vane sheet	12' No. 8
168	.25	Lug on vane for No. 123	8'-10'-12' No. 7
168N	.20	Lug on vane for No. 123	6' No. 7
168Q	1.18	Regulating spring	8' Nos. 8-10
168½QQ	1.89	Regulating spring	10' Nos. 8-10
168½Z	3.08	Regulating spring	12' Nos. 8-10
169A	.67	Vane cross piece (long)	All 8' mills
169B	.67	Vane cross piece (long)	All 10' mills
169C	1.68	Vane cross piece (long)	All 12' mills
169N	.34	Vane cross piece (long)	6' No. 7
170A	.67	Vane cross piece (medium)	All 8' mills
170B	.67	Vane cross piece (medium)	All 10' mills
170C	1.54	Vane cross piece (medium)	All 12' mills
170N	.27	Vane cross piece (medium)	6' No. 7
170½C	1.89	Vane cross piece (long medium)	All 12' mills
171A	.50	Vane cross piece (short)	All 8' mills
171B	.50	Vane cross piece (short)	All 10' mills
171C	1.47	Vane cross piece (short)	All 12' mills
171N	.25	Vane cross piece (short)	6' No. 7
172A	.42	Vane strap (long)	All 8' mills

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
172B	.42	Vane strap (long).....	All 10' mills
172C	.92	Vane strap (long).....	All 12' mills
172N	.34	Vane strap (long).....	6' No. 7
173A	.34	Vane strap (short).....	All 8' mills
173B	.34	Vane strap (short).....	All 10' mills
173C	.84	Vane strap (short).....	All 12' mills
174Q	.08	Guide for brake band	8'-10' No. 8
174Z	.34	Guide for brake band	12' No. 8
175A	2.10	Vane sheet	8' Nos. 7-10
175B	2.38	Vane sheet	10' Nos. 7-10
175C	4.20	Vane sheet	12' Nos. 7-10
175N	1.68	Vane sheet	6' No. 7
175Q	.17	Long lug for gear cover	8' No. 8
175QQ	.25	Long lug for gear cover	10' No. 8
175Z	.25	Long lug for gear cover	12' No. 8
176Q	.17	Short lug for gear cover	8' No. 8
176QQ	.17	Short lug for gear cover	10' No. 8
176Z	.25	Short lug for gear cover	12' No. 8
177A	.08	Key for small gear	8' No. 8
177B	.17	Key for small gear	10' No. 8
177C	.42	Key for small gear	12' No. 8
178Q	.17	Small cover for oil box, O. S.	All No. 8
179Q	.08	Cable wick feed	All No. 8
180Q	.92	Arm casting	8' No. 8
180QQ	1.26	Arm casting	10' No. 8
180Z	2.03	Arm casting	12' No. 8
181Q	.17	Eye rod for regulator	8' Nos. 8-10
181Z	.17	Eye rod for regulator	10'-12' Nos. 8-10
182Q	.17	"S" hook for regulator	8'-10' Nos. 8-10
182Z	.42	"S" hook for regulator	12' Nos. 8-10
183Q	.17	Chain for regulating spring	8' Nos. 8-10
183QQ	.25	Chain for regulating spring	10' Nos. 8-10
183Z	.50	Chain for regulating spring	12' Nos. 8-10
411	1.61	Bed plate for wood tower	8'-10' No. 10; 10' No. 8
411B	2.24	Bed plate for wood tower	12' Nos. 8-10
467	.59	Pull out wire	All mills
1002	3.50	Vane casting	8' No. 10
1002B	4.34	Vane casting	10' No. 10
1002C	5.74	Vane casting	12' No. 10
1005	2.31	Rocker arm	8' No. 10
1005B	2.45	Rocker arm	10' No. 10
1005C	5.74	Rocker arm	12' No. 10
1006	.67	Flat bar connection	8'-10' No. 10
1006C	.92	Flat bar connection	12' No. 10
1009	.42	Sheave	8'-10'-12' No. 10
1010	1.34	Pitman, less box	8' No. 10
1010	1.54	Pitman, with box	8' No. 10
1010B	1.54	Pitman, less box	10' No. 10
1010B	1.82	Pitman, with box	10' No. 10
1010C	2.38	Pitman, less box	12' No. 10
1010C	2.73	Pitman, with box	12' No. 10
1010½	.25	Pitman box	8' No. 10
1010½B	.25	Pitman box	10' No. 10
1010½C	.34	Pitman box	12' No. 10
1012	.50	Pin for vane casting	8' No. 10
1012B	.50	Pin for vane casting	10' No. 10
1012C	.50	Pin for vane casting	12' No. 10
1014	.59	Pipe for No. 1005	8' No. 10
1014B	.67	Pipe for No. 1005B	10' No. 10
1014C	.84	Pipe for No. 1005C	12' No. 10
1015	.50	Pin for Nos. 1005-1006-1010	8' No. 10
1015B	.50	Pin for Nos. 1005B-1006-1010B	10' No. 10
1015C	.76	Pin for Nos. 1005C-1006C-1010C	12' No. 10

NUMERICAL LIST OF REPAIRS FOR STEEL MILLS

(Continued)

Nos. 7-8-10

No. Casting	List	NAME	Used on Mill No.
1016	2.80	Sheave arm	8' No. 10
1016B	3.08	Sheave arm	10' No. 10
1016C	4.55	Sheave arm	12' No. 10
1018	.42	Brake lever	8'-10'-12' No. 10
1022	1.82	Gear guard	8' No. 10
1022B	2.73	Gear guard	10' No. 10
1022C	4.62	Gear guard	12' No. 10
1023	1.82	Gear guard	8' No. 10
1023B	2.73	Gear guard	10' No. 10
1023C	4.62	Gear guard	12' No. 10
1024	1.26	Vane support	8' No. 10
1024B	1.47	Vane support	10' No. 10
1024C	1.82	Vane support	12' No. 10
1025	.84	Long cap	8' No. 10
1025B	.92	Long cap	10' No. 10
1025C	1.26	Long cap	12' No. 10
1029	.17	Spring for brake	8'-10'-12' No. 10
1031	.34	Brake rod casting	8'-10'-12' No. 10
1032	.34	Brake rod	8' No. 10
1032B	.50	Brake rod	10' No. 10
1032C	.67	Brake rod	12' No. 10
1033	.25	Set collar for No. 1032	8'-10'-12' No. 10
1042	1.05	Wheel arm	8' No. 10
1042B	1.47	Wheel arm	10' No. 10
1042C	2.45	Wheel arm	12' No. 10
1043	6.30	Wheel spider	8' No. 10
1043B	11.06	Wheel spider	10' No. 10
1043C	16.80	Wheel spider	12' No. 10
1045	4.06	Crank shaft	8' No. 10
1045B	6.58	Crank shaft	10' No. 10
1045C	15.12	Crank shaft	12' No. 10
1046	2.44	Wheel shaft	8' No. 10
1046B	3.71	Wheel shaft	10' No. 10
1046C	7.56	Wheel shaft	12' No. 10
1048	.67	Brake band	8' No. 10
1048B	.84	Brake band	10' No. 10
1048C	1.54	Brake band	12' No. 10
1052	.17	Cover for wheel shaft	8' No. 10
1052B	.25	Cover for wheel shaft	10' No. 10
1052C	.25	Cover for wheel shaft	12' No. 10
1057	.34	Key for spider	8' No. 10
1057B	.42	Key for spider	10' No. 10
1057C	.42	Key for spider	12' No. 10
1058C	.84	Brace for sheave arm	12' No. 10
1074	.08	Guide for No. 1048	8'-10' No. 10
1074C	.08	Guide for No. 1048C	12' No. 10
1075	3.50	Large gear	8' No. 10
1075B	5.60	Large gear	10' No. 10
1075C	8.96	Large gear	12' No. 10
1076	1.26	Small gear	8' No. 10
1076B	2.10	Small gear	10' No. 10
1076C	3.29	Small gear	12' No. 10
1077	.17	Key for small gear	8' No. 10
1077B	.17	Key for small gear	10' No. 10
1077C	.25	Key for small gear	12' No. 10
1078	2.73	Pipe for No. 1001	8'-10' No. 10
1078C	3.08	Pipe for No. 1001C	12' No. 10
1080	.67	Arm casting	8'-10' No. 10
1080C	1.26	Arm casting	12' No. 10
	2.25	Wheel section	8' No. 7
	2.75	Wheel section	8' Nos. 7-8-10
	3.00	Wheel section	10' Nos. 7-8-10
	5.90	Wheel section	12' Nos. 7-8-10